10 may 10 mg

	ERRS 7
	PAGE 1 OF 2
DAILY WO	RK ORDER / REPORT
SITE NAME: MARCO S - 98	DATE: 8/14/98
ORDER NUMBER: 0024	CONTRACT NO:68-S7-7001
ON SCENE COORDINATOR: JANICE KROONE	RESPONSE MANGER:RON LYBARGER
MONITORS: E.P.A	CONTRACTOR: IT CORPORATION
WORK AUTHORIZED	WORK ACCOMPLISHED
WORK ADMICKEED	WORK ACCOMINEDATES
Industrial Construction on site	Setting up enclosure for asbestos removel
massial Construction on site	Removed brick from around the side of the boiler
<del></del>	Tremoved blick from around the side of the bollet
<del>, , , , , , , , , , , , , , , , , , , </del>	
<del></del>	
<del></del>	<del>-</del>
	<del></del>
	<del></del>
	<del></del>
·	
· · · · · · · · · · · · · · · · · · ·	
	MININ 16 IN
	SUPERFUND RECORDS
<del></del>	SUPERFUND RECORDS
<del></del>	
<del></del>	<del></del>
<del></del>	<del></del>
	<del> </del>
OSC SIGNATURE BIG IN SIGNATURE	OSC SIGNATURE RM SIGNATURE
OSC SIGNATURE PIG 198 RM SIGNATURE	OSC PONTONE KING GIOTATORE
BOHLES BELLIA TO P. O.	March VI
har the	Volley to the thouse
	The state of the s
	MAKOO
	XQDesuggistion
	2 6
	With the state of
	:
	8 74 98 × 10 11
	-
